Figure E-10 Statutory Checklist

STATUTORY CHECKLIST [§58.35(a) activities]

for Categorical Exclusions and Environmental Assessments

Note: Review of the items on this checklist is required for both Categorical Exclusions under Sec. 58.35(a) and projects requiring an Environmental Assessment under Sec. 58.36. If no compliance with any of the items is required, a Categorical Exclusion [58.35(a)] may become "exempt" under the provisions of Sec. 58.34 (a) (12). In such cases attach the completed Statutory Checklist to a written determination of the exemption. Projects requiring an Environmental Assessment under Sec. 58.36 cannot be determined to be exempt even if no compliance with Statutory Checklist items is found. Three items listed at Sec. 58.6 are applicable to all projects, including those determined to be exempt.

Project Name and Identification No. Project 2158 - 70-72 Kent Avenue, Bridgeport CT

Area of Statutory or Regulatory Compliance	Not Applicable to This Project	Consultation Required*	Review Required*	Permits Required*	Determination of consistency Approvals, Permits Obtained*	Conditions and/or Mitigation Actions Required	Provide compliance documentation. Additional material may be attached.		
Document Laws and authorities listed at 24 CFR Sec. 58.5									
Historic Properties [58.5(a)] [Section 106 of NHPA]							See attachment 1 for determination statement from CT State Historic Preservation Office. Project activities will have no adverse effects on the state of Connecticut's historic resources.		
2. Floodplain Management [58.5(b)] [Ex Or 11988] [24 CFR 55]							National Flood Insurance Program (NFIP), Flood Insurance Rate Map (FIRM) Number 09001C0433G, Revised July, 8, 2013 Identifies the property at 70-72 Kent Avenue, outside Zone A and AE for a 100 Year Flood. See attachment 2 for documentation.		
3. Wetland Protection [58.5 (b)]							United States Fish and Wildlife Services (USFWS), National Wetlands Inventory (NWI) mapping identifies the project site outside a wetland zone. See attachment 3 for map documentation. Mapping is Geographic Information System (G.I.S.) map created using data accessed from USFWS NWI website at http://www.fws.gov/wetlands/Data/State-Downloads.html		
4. Coastal Zone Management [58.5(c)]							Site at 70-72 Kent Avenue is shown located outside the Coastal Boundary Area. See attachment 4 for map documentation. Mapping is Geographic Information System (G.I.S.) map created using data accessed from CT Environmental Conditions Online (CT ECO) of the Coastal Boundary Zone from http://www.cteco.uconn.edu/		
5. Water Quality – Aquifers [58.5(d)] [40 CFR 149]	\boxtimes						On site water and sewer facilites are not included in rehabilitation work for 70-72 Kent Avenue. Connecticut DEEP Bureau of Water Protection and Land Reuse map titled 'Connecticut Aquifer Protection Areas' dated December 16, 2013 does not identify aquifer protection areas in the City of Bridgeport Connecticut near the project site. See attachment 5 for documentation		

	T	r			r	r	
Area of Statutory or Regulatory Compliance					_ *_		Provide compliance documentation. Additional material may be attached.
o o mpilatio	Not Applicable to This Project				Determination of consistency Approvals, Permits Obtained*	Conditions and/or Mitigation Actions Required	
	l is F	ired*			onsis	Mittiga	
	₽ 1	Consultation Required*	*pe	*per	of co	d/orl	
	Sable	ioi	equi	equi	ation s, Pe	s an equi	
) ppl	ultat	Review Required*	Permits Required*	min	lition IS R	
	Not/	Cons	Revi	Реш	Dete	Conc	
6. Endangered Species		[[]				Project is located outside mapped Natural Diversity Data Base
[58.5(e)] [16 U.S.C. 1531 et seq.]		l		ш			(NDDB) areas from CT DEEP. See attachment 6A for
							Geographic Information System (G.I.S.) map of NDDB areas
							created using data accessed from Connecticut Environmental
							Conditions Online (CT ECO) at http://www.cteco.uconn.edu/. U.S. Fish & Wildlife Servce Information, Planning, and
							Conservation (IPaC) List, included as attachment 6B, does not
			;				identify any Endangered Species, Critical Habitats, or Wildlife
							Refugees in the project site.
7. Wild and Scenic Rivers							Project site is not proximate to the Eight Mile River or the
[58.5 (f)] [16 U.S.C. 1271 et seq.]							Farmington River West Branch listed in the National Wild and Scenic Rivers System.
8. Air Quality		\vdash			$\overline{}$		No quantifiable increase in air pollution is measurable for
[58.5(g)] [42 U.S.C. 7401 et seq.]			<u> </u>	ш	Ш	ш	proposed rehabilitation activities.
				_			
9. Farmland Protection					Ш		All activity will occur inside existing structure foot print and no
[58.5(h)]							change in land use is proposed.
Manmade Hazards		П		[]			Per 24 CFR 51 Subpart C and HUD Guidebook 6600.G
10 A. Thermal Explosive					Laured		rehbilitation work that does not alter the number dwelling units
[58.5(i)]							or a change of land use is not subject to Acceptable Separation
							Distance (ASD) requirements for HUD assisted projects near hazardous operations handling petroleum products or
							chemicals of an explosive or flammable nature.
10 B. Noise		П	\Box	П	П		Noise Abatement and Control requirements per 24 CFR
[58.5(i)]	k3		LJ				51.101(a)(3) are not applicable to HUD assisted projects which
100	K 7	<u></u>					restore facilities substantially as they existed prior to a disaster.
10 C. Airport Clear Zones [58.5 (i)]		Ш			$ \sqcup $		The residential structure at 70-72 Kent Avenue is located
[56.5 (V)]							outside the Runway Clear Zone of Tweed/New Haven Commercial Airport.
10 D. Toxic Sites	X	П	П	П		П	The project site at 70-72 Kent Avenue, Bridgeport CT is,
[58.5 (i)(2)(i)]			<u></u>			ш	
							Not listed on EPA's NPL Lists (Proposed and Final) or the State of Connections's Superfund Brigging Lists
							the State of Connecticut's Superfund Priority List; 2. Not listed in Comprehensive Environmental
							Response and Compensation Liability Infomration
							System (CERCLIS) database search as a
							Comprehensive Environmental Response and
							Compensation Liability Act (CERCLA) site;
							3. Not located within 3,000 feet of a landfill site as listed
							on CT DEEP's active landfill list;
	1						Not listed on CT DEEP's Underground Storage Tank
							list
							5. Not listed on CT DEEP's list of potentionally
							contaminated sites and is not known or suspected to

	т	,	,				
Area of Statutory or Regulatory Compliance	Not Applicable to This Project	Consultation Required*	Review Required*	Permits Required*	Determination of consistency Approvals, Permits Obtained*	Conditions and/or Mitigation Actions Required	Provide compliance documentation. Additional material may be attached.
							be contaminated by toxic chemicals or radioactive materials
11. Environmental Justice [58.5(j)]							The rehabilitation work at the project site, 70-72 Kent Avenue, is compatible with the surrounding residential use and no adverse human health and environmental effects on minority or low income populations are expected. The city of Bridgeport, Connecticut is listed by the Connecticut Department of Economic and Community Development (CT DECD) as a distressed municipality as defined in C.G.S. Section 22a-20. See attachment 7 for the 2013 listing of distressed municipalities in CT from the CT DECD in which Bridgeport, CT is listed.
Document Laws and at	ıthoı	rities	s list	ed a	t Sec.	58.6	and other potential environmental concerns
12 A. Flood Insurance [58.6(a) & (b)]							National Flood Insurance Program (NFIP), Flood Insurance Rate Map (FIRM) Number 09001C0433G, Revised July, 8, 2013 Identifies the property at 70-72 Kent Avenue, outside Zone A and AE for a 100 Year Flood. See attachment 2 for documentation.
12 B. Coastal Barriers [58.6(c)]							Project at 70-72 Kent Avenue, Bridgeport CT is not located within a Coastal Barrier Resource System unit. See attachment 8 for documentation. Mapping is Geographic Information System (G.I.S.) map created using data digitized from official John H. Chafee Coastal Barrier Resource System maps enacted by law and endorsed by the U.S. Fish and Wildlife Service. Digital data was accessed from CT Environmental Conditions Online (CT ECO) at http://www.cteco.uconn.edu/
12 C. Airport Clear Zone Notification [58.6(d)]							Project does not involve the puchase or sale of a property as such 24 CFR 58.6(d) is not applicable.
13 A. Solid Waste Disposal [42 U.S.C. S3251 et seq.] and [42 U.S.C. 6901-6987 eq seq.]	\boxtimes						Rehabilitation activities to the residential structure at the project site, 70-72 Kent Avenue, are not expected to affect the capacities of solid waste disposal services.
13 B. Fish and Wildlife [U.S.C. 661-666c]	\boxtimes						Project activites will not result in impounding, diverting, deepening, channelizing or modification of any stream or body of water. Project is not a water control project.
13 C. Lead-Based Paint [24 CFR Part 35] and [40 CFR 745.80 Subpart E]							Residential Structure at 70-72 Kent Avenue was built prior to 1978. The results of a Lead Paint Survey are included in attachment 9, 'Hazardous Materials Inspection Report, 70-72 Kent Avenue Bridgeport, CT', 11 July 2014, prepared by Facility Support Services, LLC. Lead based paint hazards identified in the survey will be abated or addressed with interim controls where appropriate per attachment 10, 'Abatement Plan for 70 Kent Ave., First Floor, Bridgeport, Ct' and attachment 11,

Area of Statutory or Regulatory Compliance	Not Applicable to This Project	Consultation Required*	Review Required*	Permits Required*	Determination of consistency Approvals, Permits Obtained*	Conditions and/or Mitigation Actions Required	Provide compliance documentation. Additional material may be attached.
							'Lead Hazard Remediation Project, 72 Kent Avenue, Second and Third Floors, Bridgeport, CT' prepared by Gilbertco Lead Inspections LLC.
13 D. Asbestos							No Asbestos Containing Materials (ACM's) were identified in sampled materials to be disturbed by project work. Results of sampled materials testing are included in attachment 9, 'Hazardous Material Inspection Report, 70-72 Kent Avenue, Bridgeport, CT", 11 July 2014, prepared by Facility Support Services, LLC.
13 E. Radon [50.3 (i) 1]							Radon levels requiring mitigation were not found at the project site. Results of testing are included in attachment 9, 'Hazardous Material Inspection Report, 70-72 Kent Avenue, Bridgeport, CT', 11 July 2014, prepared by Facility Support Services LLC.
13 F. Mold							No specific regulation regarding the levels requiring mold mitigation or abatement are enacted by law in the State of Connecticut. Accelerated mold growth is not indicated by testing results at the project site. The procedures and results of the microbial testing for mold spores conducted at the project site are included in attachment 9, 'Hazardous Material Inspection Report, 70-72 Kent Avenue, Bridgeport, CT', 11 July 2014, prepared by Facility Support Services, LLC.
Other: State or Local 14 A. Flood Management Certification [CGS 25-68]	\boxtimes						National Flood Insurance Program (NFIP), Flood Insurance Rate Map (FIRM) 09001C0433G, Revised July, 8, 2013 Identifies the property at 70-72 Kent Avenue, outside Zone A and AE for a 100 Year Flood. See attachment 2 for documentation.
14 B. Structures, Dredging & Fill Act [CGS 22a-359 to 22a-363f]							Rehabilitation work at project site does not propose any adverse impacts to coastal resources nor propose any activity waterward of the coastal jurisdiction line.
14 C. Tidal Wetlands Act [CGS 22a-28 to 22a-35]							Connecticut Department of Energy and Environmental Protection Tidal Wetlands Mapping as defined in C.G.S. Section 22a-29 and Section 22a-93(7)(e) identifies the project as outside a Tidal Wetland Zone. See attachment 14 for documentation. Mapping is Geographic Information System (G.I.S.) map created using data accessed from CT Environmental Conditions Online (CT ECO) of Tidal Wetlands Mapping accessed from http://www.cteco.uconn.edu/
14 D. Local inland wetlands/watercourses [CGS 22a-42]							Project rehabilitation work is not expected to impact wetlands/watercourses.
14 E. Various municipal zoning approvals							Rehabilitation activites at the project site will need review by City of Bridgeport, CT Building Department for issuance of required building permit.

DETERMINATION: This project converts to Exempt, per \$158.34 requires any formal permit or license. Fund	19a)(12), because it does not require any mitigation for compiance with any listed statutes or authorities, no is may be drawn down for this (now) EXEMPT project; <u>OR</u>
This project cannot convert to Exempt becar requirements, publish NOI/RROF and obtain	use one or more statutes/authories requires consultation or itigation. Complete consultation/mitigation nature of the Authority to Use Grant Funds (HUD 7015.16) per 1,58.70 and 58.71 before drawing down funds; OR
The unusual circumstances of this project m Assessment (EA). Prepare the EA according	nay reasult in a significant environmental impact. This project requires preparation of an Environmental ig to 24 CFR Part 58 Subpart E.
Prepared by	7/23/14
Richard Couch, P.E., Member Martinez Couch & Associates, LLC.	Date
Responsible Entity or designee Signature: Hermia Detaire, EDBG-DR Program Manager	Date 10/1/14



1084 Cromwell Avenue Suite, A-2 Rocky Hill, CT 06067 Tel: 860-436-4364 Fax: 860-436-4626 www.martinezcouch.com

Attachment 1 - Checklist Item # 1 Documentation - CT SHPO Determination Statement



Department of Economic and Community Development



2158 p

May 28, 2014

Ms. Hermia M. Delaire
Program Manager
CDBG - Sandy Disaster Recovery Program
Department of Housing
505 Hudson Street
Hartford, CT 06106

Subject:

70-72 Kent Avenue

Bridgeport, CT

Dear Ms. Delaire:

The State Historic Preservation Office has reviewed the information submitted for the above-named property pursuant to the provisions of Section 106 of the National Historic Preservation Act of 1966.

The property located at 70-72 Kent Avenue appears to be eligible for listing on the National Register of Historic Places as a contributing resource to a potential historic district.

Your work plan dated 4/17/14 includes replacement of damaged screens and storm windows, repair of three damaged windows, replacement glazing for the rear storm door. Interior work includes patching of the drywall ceiling, replacement of the storage sidewalls and repair of the damaged wood floor.

The SHPO has determined that the undertaking as proposed will constitute <u>no</u> adverse effects to historic resources.

The State Historic Preservation Office appreciates the opportunity to review and comment upon this project. These comments are provided in accordance with the Connecticut Environmental Policy Act and Section 106 of the National Historic Preservation Act. For further information please contact Todd Levine, Environmental Reviewer, at (860) 256-2759 or todd.levine@ct.gov.

Sincerely,

Mary B. Dunne

Deputy State Historic Preservation Officer